




GARY R. HERBERT  
Governor  
GREGORY S. BELL  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
**November 1, 2011**

Reviewed: 

<b>Mine Name:</b> Solar Wind	<b>Permit Number:</b> S/023/0061
<b>Operator Name:</b> Got Named Inc.	<b>Inspection Date:</b> October 26, 2011
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 4:00-4:20 PM
<b>Other Participants:</b>	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

This was a routine inspection.

**Inspection Summary:**

The ownership has changed and the mine is now controlled by Got Named Inc. The BLM holds a bond for \$ 6,365 and the Division holds 1,035.00 for a total bond of \$7,400.00. The BLM bond was transferred from the old operator to the new operator.


The site is small less than one acre.

During the inspection there were caterpillar type track marks on the property. Who was on the property is unknown as final approval for Got Named Inc. to conduct mining was not granted by the Division until early November 2011.

**Conclusions and Recommendations:**

The Division should continue to monitor this site. The mine is visible from the Pony Express Road and visible to the public.

**Inspector's Signature**



WHW:

cc: (OPERATOR)

Jerry Mansfield, BLM

O:\M023-Juab\S0230061-SolarWind\inspections\Insp10262011.doc



Waste pile looking east



Highwalls looking east



Highwalls looking south



Highwalls looking west